

The assembly of water-lifting equipment envisages two stages:


- *assembly of pumping equipment in the well;*
- *assembly of equipment in the engineering and utility services room.*

Before starting assembling works, it is important to select correctly the pumping equipment, proceeding from the well parameters. Otherwise, the expensive equipment will fail, leaving the owner without water.

The pump is *the “heart”* of the well.

The simplest diagram of assembly of the pumping equipment is shown on *fig. 1*

The water supply company “Burvod” collaborates with the followings suppliers



and producers of pumping equipment:

- *Saer (Italy)*
- *Pedrolo (Italy)*
- *Calpeda (Italy)*
- *Willo (Germany)*
- *Grundfos (Germany)*
- *As well as domestic producers*

